



## *Candle utility*

- Before burning the candle cut the wick up to no more of 1,5 cm of height.
- Never leave the candle unattended.
- If the candle makes smoke, light off the candle and cut the wick.
- Remove all the wick's residues.
- Burn the candle only on a heat-resistant surface or on an appropriate candle-hold.
- Burn the candle only far away from flammable materials.
- Do not burn the candle for more than 4 consecutive hours.
- Always store the candle far away from the sun light.
- Do not move the candle while it is burning or when the wax is still in liquid form.
- Light off the candle with an appropriate fire extinguishing tool or dip the wick in the liquid wax in order to light out the flame, later put the wick in the right position.